



The arrows indicate the columns which are to be connected to the electrowelded NET. WARNING: the non-observance of these instructions could cause serious problems to the reading and/or precision of the wood probes.



IMPORTANT
the electrowelded nets must be joined and welded together

The copper rods ensure the earthing thanks to a connection with a cable or a flat.
The earthing of the drying plant must be connected to the earth ring of the production site (factory) with a cable 50 mm². The ground (earth) of the feeding line of the kiln must be connected to ground (earth) of the drying chamber.



| | | | | | | |
|-------|----------|-------------|--|---|-------------|-----------|
| c | | | | | | |
| b | | | | | | |
| a | | | | | | |
| mod. | data | Descrizione | | DISEGNATORE | CONTROLLATO | APPROVATO |
| DATA | 24/05/13 | | | DISEGNATORE | CONTROLLATO | APPROVATO |
| FIRMA | Cavinato | | | QUOTE SENZA TOLLERANZA FARE RIFERIMENTO ALLA UNI 5307 | SCALA 1:50 | |

DENOMINAZIONE DISEGNO
Foundation plan 1EPL 65.72.41
— earthing

DITTA COMMISSIONE
AS AGROSILVA
2FAST4YOU OU



| | | | |
|------------|---------|--------|-----------|
| COMMESSA | N° DIS. | TAVOLA | IND. MOD. |
| 642.13/FAS | 6089 | 3/4 | |