


Measurements

Sp1	3,2 °C
Sp2	-7,0 °C

Parameters

Emissivity	0.95
Refl. temp.	20 °C

14.02.2021 11:16:32



14.02.2021 11:16:32



Pööning. Vaade pööningule pääsust Nele toa suunas.


Measurements

Sp1	-7,0 °C
Sp2	-5,5 °C
Sp3	-4,7 °C
Sp4	1,2 °C
Sp5	-1,9 °C

Parameters

Emissivity	0.95
Refl. temp.	20 °C

14.02.2021 11:09:12




FLIR0099.jpg

FLIR E6

63993964

14.02.2021 11:09:12



FLIR0099.jpg

FLIR E6

63993964

Köögi aknad I korrusel

Krislini tuba vasakul II korrusel, Ly tuba paremal II korrusel.

Sp2 ja Sp3 kütavad radiaatorid, Sp4 köögi aknaraam, Sp5 küttev radiaator.


Measurements

Sp1	-3,9 °C
Sp2	-8,5 °C
Sp3	-7,0 °C


Parameters

Emissivity	0.95
Refl. temp.	20 °C

14.02.2021 11:07:38



14.02.2021 11:07:38



FLIR0095.jpg

FLIR E6

63993964

Köögi lagi ja Ly toa sein II korrusel + II korruse rõdu uks.


Measurements

Sp1	-7,1 °C
Sp2	-1,8 °C
Sp3	-6,3 °C
Sp4	-4,6 °C

Parameters

Emissivity	0.95
Refl. temp.	20 °C

14.02.2021 11:06:10



FLIR0091.jpg

FLIR E6

63993964

14.02.2021 11:06:10



FLIR0091.jpg

FLIR E6

63993964

Köögi aknad I korrusel ning sauna akand soklil.


Measurements

Sp1	-4,6 °C
Sp2	-7,2 °C
Sp3	-0,1 °C

Parameters

Emissivity	0.95
Refl. temp.	20 °C

14.02.2021 11:05:53



14.02.2021 11:05:53



Köögi lagi I korrusel ja Krislini tuba vasakul II korrusel, Ly tuba paremal II korrusel.
Sp1 Küttev radiaator seina taga.

Measurements

Sp1	-7,7 °C
Sp2	-4,2 °C
Sp3	-4,0 °C
Sp4	-3,4 °C
Sp5	-4,9 °C

Parameters

Emissivity	0.95
Refl. temp.	20 °C

14.02.2021 11:05:28



FLIR0085.jpg

FLIR E6

63993964

14.02.2021 11:05:28



FLIR0085.jpg

FLIR E6

63993964

Elutuba I korrusel. Kelder soklis.


Measurements

Sp1	-8,0 °C
Sp2	-6,6 °C
Sp3	-1,3 °C

Parameters

Emissivity	0.95
Refl. temp.	20 °C

14.02.2021 11:05:20



FLIR0083.jpg

FLIR E6

63993964

14.02.2021 11:05:20



FLIR0083.jpg

FLIR E6

63993964

II korruse suur magamistuba. Elutoa lagi.


Measurements

Sp1	-9,3 °C
Sp2	-6,2 °C
Sp3	-1,2 °C
Sp4	-3,5 °C
Sp5	-3,3 °C
Sp6	-4,5 °C

Parameters

Emissivity	0.95
Refl. temp.	20 °C

14.02.2021 11:04:55



14.02.2021 11:04:55



Köögi aken I korrusel, sauna sein sokli vasakus nurgas, sokli paremas servas katlaruumi luuk.
Sp2 - mitteküttev radiاتور (pealevool maha keeratud).

Measurements

Sp1	-8,5 °C
Sp2	-3,8 °C
Sp3	-6,1 °C

Parameters

Emissivity	0.95
Refl. temp.	20 °C

14.02.2021 11:04:47



FLIR0079.jpg

FLIR E6

63993964

14.02.2021 11:04:47



FLIR0079.jpg

FLIR E6

63993964

Köögi lagi I korrusel, II korrusel Ly toa sein (ilma küttekehata).


Measurements

Sp1	-8,5 °C
Sp2	-6,3 °C
Sp3	0,0 °C
Sp4	-6,2 °C
Sp5	-1,3 °C

Parameters

Emissivity	0.95
Refl. temp.	20 °C

14.02.2021 11:03:57



FLIR0075.jpg

FLIR E6

63993964

14.02.2021 11:03:57



FLIR0075.jpg

FLIR E6

63993964

Garaaži uks, Sp4 - radiaator väikesel võimsusel (II aste, IVst).


Measurements

Sp1	-8,2 °C
Sp2	0,2 °C
Sp3	-5,5 °C
Sp4	0,5 °C
Sp5	-7,2 °C

Parameters

Emissivity	0.95
Refl. temp.	20 °C

14.02.2021 11:03:47



FLIR0073.jpg

FLIR E6

63993964

14.02.2021 11:03:47



FLIR0073.jpg

FLIR E6

63993964